



ITANOVIN.Inc

18 SEPT - 03 OCT, 2023 DRY DOCK

Air intakes restoration

*** The old paint layer was removed by chipping and polishing.

*** Repairs were made, where this intervention was necessary.

*** Layers of paint have been applied.



INDUSTRIAL ENGINEERING & SOLUTIONS

Branch 1. USA

Address: 150 SE 2 Avenue, suite 1010
MIAMI, FL 33131
TIN: 36-4839487
Cell: +1 (747) 252 9194

Branch 2. ITALY

Address: Molo Ponte Morosini
16126 GENOVA
P.Iva: 02278920992
Cell: +39 345 6675 772

Projects REPORT

Content:

A. Projects carry out on board the ship

Air Intake Restoration



Air Intake Restoration Dk 6 aft

BEFORE



DURING



AFTER



INDUSTRIAL ENGINEERING & SOLUTIONS

Branch 1. USA

Address: 150 SE 2 Avenue, suite 1010
MIAMI, FL 33131
TIN: 36-4839487
Cell: +1 (747) 252 9194

Branch 2. ITALY

Address: Molo Ponte Morosini
16126 GENOVA
P.Iva: 02278920992
Cell: +39 345 6675 772

Projects REPORT

Content:

A. Projects carry out
on board the ship

Air Intake Restoration

Air Intake Restoration Dk 8 aft

BEFORE



DURING



AFTER



INDUSTRIAL ENGINEERING & SOLUTIONS

Branch 1. USA

Address: 150 SE 2 Avenue, suite 1010
MIAMI, FL 33131
TIN: 36-4839487
Cell: +1 (747) 252 9194

Branch 2. ITALY

Address: Molo Ponte Morosini
16126 GENOVA
P.Iva: 02278920992
Cell: +39 345 6675 772

Projects REPORT

Content:

A. Projects carry out
on board the ship

Air Intake Restoration

A. BEFORE



A. DURING



A. AFTER



INDUSTRIAL ENGINEERING & SOLUTIONS

Branch 1. USA

Address: 150 SE 2 Avenue, suite 1010
MIAMI, FL 33131
TIN: 36-4839487
Cell: +1 (747) 252 9194

Branch 2. ITALY

Address: Molo Ponte Morosini
16126 GENOVA
P.Iva: 02278920992
Cell: +39 345 6675 772

Projects REPORT

Content:

**A. Projects carry out
on board the ship**

Air Intake Restoration

Air Intake Restoration Dk 5


B. BEFORE



B. DURING



B. AFTER



INDUSTRIAL ENGINEERING & SOLUTIONS

Branch 1. USA

Address: 150 SE 2 Avenue, suite 1010
MIAMI, FL 33131
TIN: 36-4839487
Cell: +1 (747) 252 9194

Branch 2. ITALY

Address: Molo Ponte Morosini
16126 GENOVA
P.Iva: 02278920992
Cell: +39 345 6675 772

Projects REPORT

Content:

A. Projects carry out
on board the ship

Air Intake Restoration

C. BEFORE



C. DURING



C. AFTER



INDUSTRIAL ENGINEERING & SOLUTIONS

Branch 1. USA

Address: 150 SE 2 Avenue, suite 1010
MIAMI, FL 33131
TIN: 36-4839487
Cell: +1 (747) 252 9194

Branch 2. ITALY

Address: Molo Ponte Morosini
16126 GENOVA
P.Iva: 02278920992
Cell: +39 345 6675 772

Projects REPORT

Content:

**A. Projects carry out
on board the ship**

Air Intake Restoration

Air Intake Restoration Dk 5

D. BEFORE



D. DURING



D. AFTER



INDUSTRIAL ENGINEERING & SOLUTIONS

Branch 1. USA

Address: 150 SE 2 Avenue, suite 1010
MIAMI, FL 33131
TIN: 36-4839487
Cell: +1 (747) 252 9194

Branch 2. ITALY

Address: Molo Ponte Morosini
16126 GENOVA
P.Iva: 02278920992
Cell: +39 345 6675 772

Projects REPORT

Content:

A. Projects carry out
on board the ship

Air Intake Restoration

Air Intake Restoration Dk 5

E. BEFORE



E. DURING



E. AFTER



INDUSTRIAL ENGINEERING & SOLUTIONS

Branch 1. USA

Address: 150 SE 2 Avenue, suite 1010
MIAMI, FL 33131
TIN: 36-4839487
Cell: +1 (747) 252 9194

Branch 2. ITALY

Address: Molo Ponte Morosini
16126 GENOVA
P.Iva: 02278920992
Cell: +39 345 6675 772

Projects REPORT

Content:

A. Projects carry out
on board the ship

Air Intake Restoration

F. BEFORE



F. DURING



F. AFTER



INDUSTRIAL ENGINEERING & SOLUTIONS

Branch 1. USA

Address: 150 SE 2 Avenue, suite 1010
MIAMI, FL 33131
TIN: 36-4839487
Cell: +1 (747) 252 9194

Branch 2. ITALY

Address: Molo Ponte Morosini
16126 GENOVA
P.Iva: 02278920992
Cell: +39 345 6675 772

Projects REPORT

Content:

A. Projects carry out on board the ship

Air Intake Restoration

Air Intake Restoration Dk 5

G. BEFORE



G. DURING



G. AFTER



INDUSTRIAL ENGINEERING & SOLUTIONS

Branch 1. USA

Address: 150 SE 2 Avenue, suite 1010
MIAMI, FL 33131
TIN: 36-4839487
Cell: +1 (747) 252 9194

Branch 2. ITALY

Address: Molo Ponte Morosini
16126 GENOVA
P.Iva: 02278920992
Cell: +39 345 6675 772

Projects REPORT

Content:

A. Projects carry out
on board the ship

Air Intake Restoration

H. BEFORE



H. DURING



H. AFTER



INDUSTRIAL ENGINEERING & SOLUTIONS

Branch 1. USA

Address: 150 SE 2 Avenue, suite 1010
MIAMI, FL 33131
TIN: 36-4839487
Cell: +1 (747) 252 9194

Branch 2. ITALY

Address: Molo Ponte Morosini
16126 GENOVA
P.Iva: 02278920992
Cell: +39 345 6675 772

Projects REPORT

Content:

**A. Projects carry out
on board the ship**

Air Intake Restoration

J. BEFORE



J. DURING



J. AFTER



INDUSTRIAL ENGINEERING & SOLUTIONS

Branch 1. USA

Address: 150 SE 2 Avenue, suite 1010
MIAMI, FL 33131
TIN: 36-4839487
Cell: +1 (747) 252 9194

Branch 2. ITALY

Address: Molo Ponte Morosini
16126 GENOVA
P.Iva: 02278920992
Cell: +39 345 6675 772

Projects REPORT

Content:

**A. Projects carry out
on board the ship**

Air Intake Restoration

Air Intake Restoration Dk 5

K. BEFORE



K. DURING



INDUSTRIAL ENGINEERING & SOLUTIONS

Branch 1. USA

Address: 150 SE 2 Avenue, suite 1010
MIAMI, FL 33131
TIN: 36-4839487
Cell: +1 (747) 252 9194

Branch 2. ITALY

Address: Molo Ponte Morosini
16126 GENOVA
P.Iva: 02278920992
Cell: +39 345 6675 772

Projects REPORT

Content:

A. Projects carry out
on board the ship

Air Intake Restoration

K. AFTER



INDUSTRIAL ENGINEERING & SOLUTIONS

Branch 1. USA

Address: 150 SE 2 Avenue, suite 1010
MIAMI, FL 33131
TIN: 36-4839487
Cell: +1 (747) 252 9194

Branch 2. ITALY

Address: Molo Ponte Morosini
16126 GENOVA
P.Iva: 02278920992
Cell: +39 345 6675 772

Projects REPORT

Content:

**A. Projects carry out
on board the ship**

Air Intake Restoration

L. BEFORE



L. DURING



INDUSTRIAL ENGINEERING & SOLUTIONS

Branch 1. USA

Address: 150 SE 2 Avenue, suite 1010
MIAMI, FL 33131
TIN: 36-4839487
Cell: +1 (747) 252 9194

Branch 2. ITALY

Address: Molo Ponte Morosini
16126 GENOVA
P.Iva: 02278920992
Cell: +39 345 6675 772

Projects REPORT

Content:

**A. Projects carry out
on board the ship**

Air Intake Restoration

L. AFTER



INDUSTRIAL ENGINEERING & SOLUTIONS

Branch 1. USA

Address: 150 SE 2 Avenue, suite 1010
MIAMI, FL 33131
TIN: 36-4839487
Cell: +1 (747) 252 9194

Branch 2. ITALY

Address: Molo Ponte Morosini
16126 GENOVA
P.Iva: 02278920992
Cell: +39 345 6675 772

Projects REPORT

Content:

**A. Projects carry out
on board the ship**

Air Intake Restoration

Air Intake Restoration TRUNK REPAIR - DK 5 MIDSHIP PORT

BEFORE



DURING



AFTER



INDUSTRIAL ENGINEERING & SOLUTIONS

Branch 1. USA

Address: 150 SE 2 Avenue, suite 1010
MIAMI, FL 33131
TIN: 36-4839487
Cell: +1 (747) 252 9194

Branch 2. ITALY

Address: Molo Ponte Morosini
16126 GENOVA
P.Iva: 02278920992
Cell: +39 345 6675 772

Projects REPORT

Content:

A. Projects carry out
on board the ship

Trunk repair - Dk 5 Mid Port

Air Intake Restoration TRUNK REPAIR - DK 5 AFT PORT

BEFORE



DURING



AFTER



INDUSTRIAL ENGINEERING & SOLUTIONS

Branch 1. USA

Address: 150 SE 2 Avenue, suite 1010
MIAMI, FL 33131
TIN: 36-4839487
Cell: +1 (747) 252 9194

Branch 2. ITALY

Address: Molo Ponte Morosini
16126 GENOVA
P.Iva: 02278920992
Cell: +39 345 6675 772

Projects REPORT

Content:

A. Projects carry out
on board the ship

Trunk repair - Dk 5 Mid Port



ITANOVIN.Inc

18 SEPT - 03 OCT, 2023 DRY DOCK

Air intakes restoration

*** The old paint layer was removed by chipping and polishing.

*** Repairs were made, where this intervention was necessary.

*** Layers of paint have been applied.



INDUSTRIAL ENGINEERING & SOLUTIONS

Branch 1. USA

Address: 150 SE 2 Avenue, suite 1010
MIAMI, FL 33131
TIN: 36-4839487
Cell: +1 (747) 252 9194

Branch 2. ITALY

Address: Molo Ponte Morosini
16126 GENOVA
P.Iva: 02278920992
Cell: +39 345 6675 772

Projects REPORT

Content:

A. Projects carry out on board the ship

Air Intake Restoration

